**APPENDIX D** 

SITE PHOTOGRAPHS






Photo 3: Looking northeast from southern end of northern ferry landing.






Photo 5: Panoramic view of southern landing taken from west side, paning from north (on left) to south (on right)



Photo 6: Panoramic view of southern landing paning from southwest (left) to northwest (right).

	1	Government of Northwest Territories	PROJECT NO.	i.
		Fort Providence, NWT	03-2374-1000	i.
	CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.	i.
	October 2003	SITE PHOTOGRAPHS	5.6	È.





Photo 7: Miscellaneous wood, metal and barrels in southwest corner of southern landing.



Photo 8: Miscellaneous piles of wood and metals in southwest corner of southern landing looking northwest

	Government of Northwest Territories	PROJECT NO.
	Fort Providence, NWT	03-2374-1000
<b>DILLON</b> CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.
October 2003	SITE PHOTOGRAPHS	7,8



Photo 9: East side of southern landing looking north, power house for lights located on top of berm.



Photo 10: Drainage ditch on east side of southern landing looking south.

	Government of Northwest Territories	PROJECT NO.
	Fort Providence, NWT	03-2374-1000
DILLON CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.
October 2003	SITE PHOTOGRAPHS	9,10




Photo 11: Southern landing looking north, winch house on left, elevated berm on right.





Photo 12: Southern landing looking north, western winch house on left.

	Government of Northwest Territories	PROJECT NO.
	Fort Providence, NWT	03-2374-1000
<b>DILLON</b> CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.
October 2003	SITE PHOTOGRAPHS	11,12



Photo 13: Southern landing looking east at eastern winch house.








Photo 17: Southern landing looking north, metal pipes.



Photo 18: Southern landing looking north, metal pipes.

	Government of Northwest Territories	PROJECT NO.
	Fort Providence, NWT	03-2374-1000
DILLON CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.
October 2003	SITE PHOTOGRAPHS	17,18



Photo 19: Minor oil staining around gear house on southern landing.



Photo 20: Concrete floor inside gear house.

	Government of Northwest Territories	PROJECT NO.
	Fort Providence, NWT	03-2374-1000
CONSULTING	PHASE I AND II - FORT PROVIDENCE FERRY LANDINGS	PHOTO NOS.
October 2003	SITE PHOTOGRAPHS	19,20