

TABLE DFO 2-1: FISH-BEARING CROSSINGS HABITAT (revised Oct 2016)

Road Km	Stream Name	Fish	Crossing Type	Habitat (m ²)		Comment
				Lost	Altered	
6.1	Casket Creek	Y	B	0	0	Bridge and causeway exist. New armoured footings replace existing gabion baskets.
28.6	Sundog Trib.	Y	B	0	0	Abutments above normal HWM.
39.4	Sundog Trib.	Y	B	15.0	0	15 x 1 for western abutment
45.8	Polje Trib.	Y	C	0	9.6	19.2 l x 0.5 w
49.6	Polje Trib.	?	C	0	23.0	19.2 l x 1.2 w
53.5	Polje Trib.	Y	B	0	30.7	19.2 l x 1.2 w
53.55	Polje Creek	Y	B	0	0	Abutments above normal HWM.
87.25	Tetcela Trib.	Y	B	0	0	Abutments above normal HWM.
89.8	Tetcela Main stem	Y	B	0	0	Abutments above normal HWM.
124.5	Grainger River	Y	B	0	0	15 x 5, each abutment
126.2	Grainger Trib.	N	C	0	0	21 l x 0.7 w
130.7	Grainger Trib.	N	C	0	0	Habitat Km 131.3. 21 l x 0.85 w
132.7	Grainger Trib.	N	C	0	0	Habitat Km 133.7. 21 l x 1.7 w
134.5	Grainger Trib.	N	C	0	0	Habitat Km 135.6. 21 l x 0.9 w
134.8	Grainger Trib.	N	C	0	0	Ref. Allnorth 21 l x 0.7 w
135.5	Grainger Trib.	N	C	0	0	Ref. Allnorth 21 l x 0.7 w
135.95	Grainger Trib.	N	C	0	0	Habitat Km 136.7. 21 l x 0.7 w
136.5	Grainger Trib.	N	C	0	0	Ref. Allnorth 21 l x 0.7 w
137.2	Grainger Trib.	N	C	0	0	Ref. Allnorth 21 l x 0.7 w
159.7	Liard River	Y	Ba./IB	0	2,378.8	north ramp 1,268.75, south ramp 1,110
Totals				15.0	2,442.1	

Fish: Y=Yes ?=Uncertain

Crossings: C=Culvert B=Bridge Ba.=Barge IB=Ice Bridge