



FIGURE 4.3-1: Drainage Basin Boundaries and existing Gauging Stations.

from Beak Consultants Limited (1980). Initial Environmental Evaluation for the Great Slave Bay Project - Prepared for Western Mines Ltd. Vancouver, BC: June 1980



FIGURE 4.3-2: Surface Drainage Patterns

DATE	March 30 1974
PROJECT	K-4486
DWG. NO.	

* X25 OREBODY
 ○ R100 OREBODY

CONTOUR INTERVAL - 2' ft
 SCALE
 0 200 400 600 800 1000 feet

N
 ↑

© 1974 by the U.S. Geological Survey